UKCA – RoHS declaration of conformity

Daikin Europe N.V.

declares under its sole responsibility that the products to which this declaration relates:

RXF50B5V1B, RXF60B5V1B, RXF71A5V1B, ARXF50A5V1B, ARXF60A5V1B, ARXF71A5V1B, RXP50M5V1B, RXP60M5V1B, RXP71M5V1B, RXM42R5V1B, RXM50R5V1B, RXM60R5V1B, ARXM50R5V1B, ARXM60R5V1B, ARXM71R5V1B, RXF50D5V1B, RXF60D5V1B, RXF71D5V1B, FDA125A5VEB, FAA71AUVEB, FAA100AUVEB, FVA71AMVEB, FVA100AMVEB, FVA125AMVEB, FVA140AMVEB, AVA125AMVE, FXAQ15AUV1B, FXAQ20AUV1B, FXAQ25AUV1B, FXAQ32AUV1B, FXAQ40AUV1B, FXAQ50AUV1B, FXAQ63AUV1B, FUA71AVEB9, FUA100AVEB9, FUA125AVEB9, FVXM25FV1B9, FVXM35FV1B9, FVXM50FV1B9, FHA35AVEB99, FHA50AVEB99, FHA60AVEB99, FHA71AVEB99, FHA100AVEB9, FHA125AVEB9, FHA140AVEB9, FDA200AXVEB, FDA250AXVEB, CTXM15R5V1B, FTXM20R5V1B, FTXM25R5V1B, FTXM35R5V1B, FTXM42R5V1B, ATXM20R5V1B, ATXM25R5V1B, ATXM35R5V1B, FXAA15AUV1B, FXAA20AUV1B, FXAA25AUV1B, FXAA32AUV1B, FXAA40AUV1B, FXAA50AUV1B, FXAA63AUV1B, RXJ20A5V1B, RXJ25A5V1B, RXJ35A5V1B, FAA71BUV1B, FAA100BUV1B, RXM20R5V1B9, RXM25R5V1B9, RXM35R5V1B9, ARXM25R5V1B9, ARXM35R5V1B9, RXJ20M5V1B9, RXJ25M5V1B9, RXJ35M5V1B9, RXA20A5V1B9, RXA25A5V1B9, RXA35A5V1B9, ARXQ25AMV1B, ARXQ35AMV1B, ATXQ25AMV1B, ATXQ35AMV1B, FTXQ25AMV1B, FTXQ35AMV1B, RXQ25AMV1B, RXQ35AMV1B, FXUA50AVEB, FXUA71AVEB, FXUA100AVEB, FXHA32AVEB, FXHA50AVEB, FXHA63AVEB, FXHA100AVEB, ATXP20M5V1B, ATXP25M5V1B, ATXP35M5V1B, ATXTP25M5V1B, ATXTP35M5V1B, FTXTP25M5V1B, FTXTP35M5V1B, FTXP20M5V1B9, FTXP25M5V1B9, FTXP35M5V1B9, ARXP20M5V1B, ARXP25M5V1B, ARXP35M5V1B, RXP20M5V1B, RXP25M5V1B, RXP35M5V1B, FXLQ20P5VEB, FXLQ25P5VEB, FXLQ32P5VEB, FXLQ40P5VEB, FXLQ50P5VEB, FXLQ63P5VEB, BEV2N112A7V1B, FXMA50A5VEB, FXMA63A5VEB, FXMA80A5VEB, FXMA100A5VEB, FXMA125A5VEB,

are in conformity with the following directive(s) or regulation(s), as amended:

<A> DES-PR-0015

RoHS (#) SI 2012/3032: Restriction of the Use of Certain Hazardous Substances in Electrical and Electronic Equipment Regulations 2012(*),

following the provisions of: BS EN IEC 63000.

Note* As set out in **<A>**.

Restriction **o**f Certain **H**azardous **S**ubstances in electrical and electronic equipment

4P695686-2A

DAIKIN

Hiromitsu Iwasaki
Director
Ostend, 1st of June 2022

DAIKIN EUROPE N.V.
Zandvoordestraat 300, B-8400 Oostende, Belgium