

UKCA – RoHS declaration of conformity

Daikin Industries Czech Republic s.r.o.

declares under its sole responsibility that the products to which this declaration relates:

AZQS71B2V1B, RZQSG71L3V1B, 3MXF52A2V1B9, 3AXMF52A2V1B9, 3AMXM52N2V1B9, 3MXF68A2V1B9, RXJ50N2V1B, RXA42B2V1B, RXA50B2V1B, RZAG35A2V1B, RZAG50A2V1B, RZAG60A2V1B, 2AMXF50A2V1B, RXTA30B2V1B, RXTM30R2V1B, RXTM40R2V1B, RXTP25R2V1B, RXTP35R2V1B, ARXTP25R2V1B, ARXTP35R2V1B, RXJ42A2V1B, RXJ50A2V1B, 2MXM68A2V1B, 3M XM52A2V1B, 3M XM68A2V1B, 4MXM68A2V1B, 4MXM80A2V1B, 5MXM90A2V1B, 4MWXM52A2V1B, 2MXM50A2V1B, RXM42R2V1B, RXM50R2V1B, RXM71R2V1B, 2MXF50A2V1B, 2MXM50N2V1B9, 2AMXM50M4V1B9, 3M XM40A2V1B, FXZQ15A2VEB, FXZQ20A2VEB, FXZQ25A2VEB, FXZQ32A2VEB, FXZQ40A2VEB, FXZQ50A2VEB, F XSQ15A2VEB, F XSQ20A2VEB, F XSQ25A2VEB, F XSQ32A2VEB, F XSQ40A2VEB, F XSQ50A2VEB, F XSQ63A2VEB, F XSQ80A2VEB, F XSQ100A2VEB, F XSQ125A2VEB, F XSQ140A2VEB, F XNQ20A2VEB, F XNQ25A2VEB, F XNQ32A2VEB, F XNQ40A2VEB, F XNQ50A2VEB, F XNQ63A2VEB, F TXJ20MV1BW, F TXJ25MV1BW, F TXJ35MV1BW, F TXJ50MV1BW, F TXJ20MV1BS, F TXJ25MV1BS, F TXJ35MV1BS, F TXJ50MV1BS, F BA100A2VEB, F BA125A2VEB, F BA140A2VEB, F XDQ15A3VEB, F XDQ20A3VEB, F XDQ25A3VEB, F XDQ32A3VEB, F XDQ40A3VEB, F XDQ50A3VEB, F XDQ63A3VEB, F XDQ15P3VE, F XDQ20P3VE, F XDQ25P3VE, F XDQ32P3VE, F XDQ40P3VE, F XDQ50P3VE, FCAG35BVEB, FCAG50BVEB, FCAG60BVEB, FCAG71BVEB, FCAG100BVEB, FCAG125BVEB, FCAG140BVEB, F CAHG71HVEB, F CAHG100HVEB, F CAHG125HVEB, F CAHG140HVEB, F XFQ20BVEB, F XFQ25BVEB, F XFQ32BVEB, F XFQ40BVEB, F XFQ50BVEB, F XFQ63BVEB, F XFQ80BVEB, F XFQ100BVEB, F XFQ125BVEB, F DXM25F3V1B9, F DXM35F3V1B9, F DXM50F3V1B9, F DXM60F3V1B9, F FA25A2VEB9, F FA35A2VEB9, F FA50A2VEB9, F FA60A2VEB9, F BA25A2VEB9, F BA35A2VEB9, F BA50A2VEB9, F BA60A2VEB9, F BA71A2VEB9, F NA25A2VEB9, F NA50A2VEB9, F NA60A2VEB9, F TXP50M2V1B, F TXP60M2V1B, F TXP71M2V1B, ADEA35A2VEB, ADEA50A2VEB, ADEA60A2VEB, ADEA71A2VEB, ADEA100A2VEB, ADEA125A2VEB, F XZA15A2VEB, F XZA20A2VEB, F XZA25A2VEB, F XZA32A2VEB, F XZA40A2VEB, F XZA50A2VEB, F XFA20A2VEB, F XFA25A2VEB, F XFA32A2VEB, F XFA40A2VEB, F XFA50A2VEB, F XFA63A2VEB, F XFA80A2VEB, F XFA100A2VEB, F XFA125A2VEB, F XSA20A2VEB, F XSA25A2VEB, F XSA32A2VEB, F XSA40A2VEB, F XSA50A2VEB, F XSA63A2VEB, F XSA80A2VEB, F XSA100A2VEB, F XSA125A2VEB, F XSA140A2VEB, F XDA10A2VEB, F XDA15A2VEB, F XDA20A2VEB, F XDA25A2VEB, F XDA32A2VEB, F XDA40A2VEB, F XDA50A2VEB, F XDA63A2VEB, F XSA15A2VEB, 2AMXF40A2V1B, 2MXM40A2V1B, F XFN50A2VEB, F XFN71A2VEB, F XFN112A2VEB, F TXF50D2V1B, F TXF60D2V1B, F TXF71D2V1B, 2AMXM40M4V1B9, 2MXF40A2V1B, F XS N50A2VEB, F XS N71A2VEB, F XS N112A2VEB, BRP069B41, BRP069B42, BRP069B43, BRP069B45, ATXM20R2V1B, ATXM25R2V1B, ATXM50R2V1B, CTXA15A2V1B, F T X A20A2V1B, F T X A25A2V1B, F T X A35A2V1B, F T X A42A2V1B, F T X A50A2V1B, F T X A63A2V1B, F T X A71A2V1B, F T X A100A2V1B, F T X A125A2V1B, F T X A15B2V1B, F T X A20B2V1B, F T X A25B2V1B, F T X A35B2V1B, F T X A42B2V1B, F T X A50B2V1B, F T X A63B2V1B, F T X A71B2V1B, F T X A100B2V1B, F T X A125B2V1B, F T X A15B2V1BB, F T X A20B2V1BB, F T X A25B2V1BB, F T X A35B2V1BB, F T X A42B2V1BB, F T X A50B2V1BB, F T X M15R2V1B, F T X M20R2V1B, F T X M25R2V1B, F T X M35R2V1B, F T X M42R2V1B, F T X M50R2V1B, F T X M60R2V1B, F T X M71R2V1B, F T X T M30R2V1B, F T X T M40R2V1B, F T X T A30B2V1B, F T X T A30B2V1BB, F T X J20A2V1B, F T X J20A2V1BS, F T X J20A2V1BB, F T X J25A2V1B, F T X J25A2V1BB, F T X J35A2V1B, F T X J35A2V1BS, F T X J35A2V1BB, F T X J50A2V1B, F T X J50A2V1BS, F T X J50A2V1BB, F T X J42A2V1B, F T X J42A2V1BS, F T X J42A2V1BB, BRP069C81, BRP069C82, CVXM20A3V1B, F VXM25A3V1B, F VXM35A3V1B, ATXF50A2V1B, ATXF60A2V1B, ATXF71A2V1B, ARXM50R2V1B, ARXM60R2V1B, ARXM71R2V1B,

are in conformity with the following directive(s) or regulation(s), as amended:

RoHS ^(#) SI 2012/3032: Restriction of the Use of Certain Hazardous Substances in Electrical and Electronic Equipment Regulations 2012(*),

following the provisions of: BS EN IEC 63000.

Note* As set out in <A>.

<A> DES-PR-0015

Restriction of Certain Hazardous Substances in electrical and electronic equipment



Yasuto Hiraoka
Managing Director
Pilsen, 1st of October 2022

DAIKIN INDUSTRIES CZECH REPUBLIC s.r.o.

U Nové Hospody 1/1155, 301 00 Plzeň Skvrňany, Czech Republic